




Continental Remediation LLC

Move the Solution, Not the Problem

Completed Project-Home Heating Oil Remediation - Egg Harbor, New Jersey

Heating Oil contamination from leaking UST extended beneath the residence, to the yard beyond. Extensive contamination was found beneath the finished basement @ 12 feet below grade. Significant resistance to injection was encountered when working through the floor. To reduce the impact on the residence from multiple injection locations through the floor, STI was flooded into the footing beneath the foundation walls at three times the amount that would have been injected through the floor.



The site has a groundwater well and septic system. The treatment will not interfere with either. Analytical results of soil samples two weeks after injection showed no contamination above NJDEP standards .

184 Riverview Avenue 2nd FL
Waltham, MA 02453-3843
Phone: 800-425-7900
Fax: 781-644-6070
Email: Info@continentalremediation.com

